



# Pianobox Pro Firmware Version Description

We are in order to solve the problem of MCU chip shortage. We added GD32 chip and APM32 chip for Pianobox Pro, previously, STM32 chip was used, so there are some differences in the upgrade program files. Please identify according to the product "S/N" number on the bottom of the product.

## 1. ST Firmware Update File

The S/N sequence appears: "LYC" or "THAPM", indicating that your machine needs to use the "ST Firmware Update File" folder. Please check out the picture below.



## 2. GD Firmware Update File

The S/N sequence appears: "THGD", indicating that your machine needs to use the "GD Firmware Update File" folder. Please check out the picture below.

